


RESISTOR INSTALLATION INSTRUCTIONS

To Reduce Input Voltage When Constant Arc'ing Occurs



- 1) TURN OFF/disconnect the electrical power to the Insect-O-Cutor® unit before proceeding with Steps 2 through 4;
- 2) Remove either the black or the white hot wire from the power supply to the transformer primary;
- 3) Splice in the RESISTOR as shown;
- 4) A second resistor may or may not be necessary in line on the other power supply line.

INSECT-O-CUTOR®

1641 Lewis Way
Stone Mountain, GA, USA 30083-1107

Telephone: (770) 939-2835

Fax: (770) 621-0100



<http://www.insect-o-cutor.com>